


























Barracuda / Weatherstrip / Rubber Bumpers, Seals & Gaskets

Picture	Product name	Description	SKU	CAD
	1964 Plymouth Barracuda License Lamp Lens Gasket	This is a factory-style replacement license lamp lens gasket.	BAICMA822084	6.70
	1964-1965 Barracuda Tail Lamp Bezel Gaskets - PR	Premium quality replacement tail lamp bezel gaskets for 1964-65 Barracuda models. These gaskets are manufactured to factory specifications from injection molded black plastic. Sold in pairs.	BAICMA3691	122.62
	1964-1965 Plymouth Barracuda Tail Lamp Gasket Set	These replacement tail lamp gaskets are laser cut to original specifications making them the most correct on the market. Each set contains the necessary gaskets for both tail lamps on one vehicle.	BAICMA822073	33.58
Early Birds Order Hotline: 1 800 463 0546				
	1964-1966 Hood Adjust Bumpers (1 1/8" OD) - Ea	Factory-style replacement hood adjust bumper for 1964-66 A and B-Body models. Designed to factory specifications and manufactured in rubber to correctly replace the hood adjust bumper. This bumper features a 1 1/8" outer diameter and measures 1-3/4" x 5/16". Sold individually.	BAICMD2080	8.38
	1964-1966 Hood Adjust Bumpers (1" OD) - Ea	Factory-style replacement hood adjust bumper for 1964-66 A and B-Body models. Designed to factory specifications and manufactured in rubber to correctly replace the hood adjust bumper. This bumper features a 1" outer diameter and measures 1-3/4" x 5/16". Sold individually.	BAICMD2079	15.10
	1964-1966 Hood Side Bumper - Ea	Factory-style replacement hood side stop bumper for various 1963-66 Mopar A-Body models. Designed to factory specifications to correctly replace the hood side stop bumper. Sold individually.	BAICMA9822	5.02
	1964-1966 Wiper Pivot Gasket Set	Replacement wiper pivot gaskets for all 1963-66 Mopar A-Body models. These gaskets are manufactured to the correct original shape to keep water from leaking into the vehicle.	BAICMA820212	18.46
	1964-1974 Body & Trunk Plugs	Body and trunk plugs in various sizes for 1960-76 Mopar models. Seal your replacement or original floor pans from road debris and water. Manufactured of rubber for original appearance, fit and	BAICMD2113	5.02











		functionRubber trunk plug for 1970-74 B-Body and E-Body models floor plug is 2-1/8" OD and fits a 1-3/4" hole (ICMD2115).Trunk plug and special socket plug for 1970-74 Barracuda and Challenger models rubber floor plug fits a hole from 1-13/16" to 1-7/8" (IC539).	Call for multiple colours, styles or patterns or choose online	
	1964-1974 Door Bumper - Ea	Factory-style replacement door rubber bumpers for various 1962-76 Mopar A, B and E-Body vehicles. Various measuring from 5/8" long, 3/4" high and 1/4" wide. Sold individually.NOTE: See image for styles.	BAICMD2067	5.02
		Call for multiple colours, styles or patterns or choose online		
	1964-1974 Firewall Washer Grommet	Factory style replacement firewall grommet for all models equipped with a foot pump washer pump. Replace your damaged or missing grommet with a brand new one.	BAICMD2163	11.74
	1964-1974 Hood Adjust Bumpers (1 1/4" OD) - Ea	Factory-style replacement hood adjust bumper for 1962-78 A, B and E-Body models. Designed to factory specifications and manufactured in rubber to correctly replace the hood adjust bumper. This bumper features a 1-1/4" outer diameter and is 1/2" thick. The overall length including the bolt is 1-3/4". Sold individually.	BAICMD2078	13.42
	1964-1974 Hood Adjust Bumpers (1 3/16" OD) - Ea	Factory-style replacement hood adjust bumper for 1962-78 A, B and E-Body models. Designed to factory specifications and manufactured in rubber to correctly replace the hood adjust bumper. This bumper features a 1-3/16" outer diameter and is 1/2" thick. The overall length including the bolt is 1-3/4". Sold individually.	BAICMD2077	8.38
	1964-1974 License Plate Bumper - Ea	Factory-style replacement license plate rubber bumper for all 1960-74 Mopar A, B and E-Body models. Sold individually.NOTE: See image for styles.	BAICMD2072	15.10
		Call for multiple colours, styles or patterns or choose online		
	1964-1974 Mopar Splash Shield Clips	Reproduction splash shield clip set for all 1962-74 Mopar models. These clips were used on various headlamp splash shields, inner fender splash shields and other splash shields. Manufactured out of stainless steel.	BAICMB281027	15.10
		Call for multiple colours, styles or patterns or choose online		
	1965 Plymouth Barracuda License Lamp Lens Gasket	This is a factory-style replacement license lamp lens gasket.	BAICMA822079	6.70
	1966 Hood To Radiator Seal	Factory-style replacement hood-to-radiator seal for various 1966 Mopar A-Body models. Manufactured to factory specifications in proper materials to correctly replace the hood to radiator seal.	BAICMA9887	75.58
				

	1966 Park Lamp Lens Gaskets - PR	Replacement park lamp lens gaskets for 1966 Mopar A-Body models. These gaskets are manufactured to fit just like the originals. Sold as a pair.	BAICMA1160	18.91
	1966 Plymouth Barracuda Tail Lamp Gasket Set	These replacement tail lamp gaskets are laser cut to original specifications making them the most correct on the market. Each set contains the necessary gaskets for both tail lamps on one vehicle.	BAICMA822074	41.98
	1966-1968 Fender Mounted Bevel Indicator Gaskets - PR	Replace dried out or missing hood or fender mounted turn signal indicator gaskets with these quality reproduction pieces.	BAICMF1711	16.78
	1966-1969 Fender Mounted Indicator Gaskets (2 Holes) - PR	Replace dried out or missing hood or fender mounted turn signal indicator gaskets with these quality reproduction pieces	BAICMF1709	16.78
	1966-1974 License Lamp Lens Gasket	Factory-style replacement license lamp lens gaskets for various 1965-74 models. Sold individually. Except 1972-74 models are sold in pairs Call for multiple colours, styles or patterns or choose online	BAICMB2212	3.34
	1966-1974 Trunk Bumper (Square Type) - Ea	Factory-style replacement trunk bumper for all 1966-74 A, B and E-Body models. Designed to factory specifications and manufactured in rubber to correctly replace the trunk bumper. Sold individually.	BAICMD2081	11.74
	1966-1974 Wiper Motor To Cowl Gasket	This replacement wiper motor to cowl gasket is designed to fit all 1966-76 Mopar A, B, and E-Body models	BAICMD600326	5.02
	1967 Hood Insert Gaskets - PR	Replacement hood insert gaskets for 1967 Barracuda models. These gaskets are manufactured out of ABS plastic and are a great replacement to your brittle factory originals.	BAICMA820168	28.54
	1967 Park Lamp Lens Gaskets - PR	Replacement park lamp lens gaskets for 1967 Mopar A-Body models. These gaskets are manufactured to fit just like the originals. Sold as a pair.	BAICMA1161	15.10
	1967-1969 A-Body Back-Up Bezel Gaskets - PR	Premium quality reproduction back-up bezel to body gasket for 1967-69 A-Body vehicles. These thin rubber strips install between the back-up bezel and the body. Sold in pairs.	BAICMA1819	25.18
	1967-1969 Back-Up Lens Gaskets	Replacement back-up lamp lens gaskets for various 1963-73 Dodge and Plymouth models. Made in USA.	BAICMA4734	21.82




	1967-1969 Hood Mounted Indicator Gaskets - PR	Replace dried out or missing hood or fender mounted turn signal indicator gaskets with these quality reproduction pieces	BAICMF1710	16.78
	1967-1969 Rubber Headlamp Splash Shields - PR	Replacement headlamp splash shields. Manufactured out of masticated rubber, with mounting hardware included. These shields mount behind the headlamps to keep debris out of the engine bay.	BAICMA820158	28.54
	1967-1969 Wiper Pivot Gasket Set	Replacement wiper pivot gaskets for all 1967-76 Mopar A-Body models. These gaskets are manufactured to the correct original shape to keep water from leaking into the vehicle.	BAICMA820213	18.46
	1967-1971 Convertible Power Top Motor Mounting Grommet - Ea	Reproduction of the original rubber mounting/insulation grommet used on various GM & Mopar vehicles with the optional power top. These rubber grommets install on the pump assembly and secure it to the vehicle while creating a damper for noise and vibration while the pump is in operation. Manufactured from high quality NBR material which is resistant to oils and fuels. Sold individually. Use as required per application	BAIC3698109	3.34
	1967-1974 Tail Lamp Gasket Sets	Replacement tail lamp gaskets for various 1965-76 models. These gaskets are laser cut to original specifications making them the most correct on the market. Each set contains the necessary gaskets to repair both tail lamps on one vehicle. Call for multiple colours, styles or patterns or choose online	BAICMA820178	47.02
	1968 Hood Insert Gaskets - PR	Replacement hood insert gaskets for 1968 Barracuda models. These gaskets are manufactured out of ABS plastic and are a great replacement to your brittle factory originals.	BAICMA820169	28.54
	1968 Velocity Stack Seals (SS/A HEMI) - PR	Factory style replacement velocity stack seals for 1968 Hemi S/S A-body models.	BAICMD2112	293.98
	1968-1974 Hood Side/Trunk Bumper - Ea	Factory-style replacement hood side stop and trunk bumper for various 1968-74 Mopar A, B and E-Body models. Designed to factory specifications to correctly replace the hood side stop or trunk bumper. Sold individually.	BAICMD2075	3.34
	1968-1974 Side Marker Lamp Gasket Set	Replacement side marker lamp gaskets for various 1968-76 A, B and E-Body models. These gaskets are laser cut to original specifications for a proper fit. Each set includes enough pieces for both sides of vehicle Call for multiple colours, styles or patterns or choose online	BAICMD600320	15.10
	1969 Park Lamp Lens Gaskets - PR	Replacement park lamp lens gaskets for 1969 Mopar A-Body models. These gaskets are manufactured to fit just like the originals. Sold as a pair.	BAICMA1162	15.10



	1970 Barracuda Tail Lamp Bezel Gaskets (.032" Gray Paper) - PR	Premium quality replacement tail lamp bezel gaskets for 1970 Barracuda models. These gaskets are manufactured to factory specifications. Sold in pairs	BAICME861029	18.46
	1970 Fender Mounted Indicator Gaskets - PR	Replace dried out or missing hood or fender mounted turn signal indicator gaskets with these quality reproduction pieces	BAICMF1715	16.78
	1970 Fiberglass Hood-to-Air Cleaner Baseplate Seal (AAR)	Replacement air cleaner hood to baseplate seal for use with 1970 'Cuda AAR and 1970 Challenger T/A models which were equipped with a fiberglass hood.	BAICMN1011	92.38
	1970 Inner Fender Rubber Splash Shields - PR	Replacement inner fender splash shields for all 1970 Mopar E-Body models. These pieces are mounted to the inner fenders, and are manufactured out of masticated rubber with stainless mounting hardware included.	BAICME861021	33.58
	1970 Park Lamp Lens Gaskets - PR	Replacement park lamp lens gaskets for 1970 Barracuda models. These gaskets are manufactured to fit just like the originals. Sold as a pair.	BAICME5064	15.10
	1970 Rear Upper Shock Plug	Replacement shock plug for all 1970 Mopar E-Body models. This piece installs on the trunk floor and covers the rear shock access hole. Two required per vehicle.	BAICME5048	15.10
	1970-1971 Gran Coupe Emblem Gasket	Replacement Gran Coupe emblem gasket for 1970-1971 Barracuda models. These gaskets are manufactured to fit just like the originals	BAREMCUD-GSK-460	15.98
	1970-1971 Shaker Air Cleaner Baseplate Seal	Replacement air cleaner hood to baseplate seal for use with 1970-71 Mopar E-Body which were equipped with a shaker hood	BAREMCLR-SLO-020	95.98
	1970-1971 Tail Lamp Bezel Gasket - 2Pc	Replacement tail lamp bezel gaskets for 1970 Barracuda models. Manufactured in the correct paper material as originals.	BAREMCUD-TLG-465	23.98
	1970-1971 Tail Lamp Gaskets - 2pc	These replacement tail lamp gaskets are laser cut to original specifications making them the most correct on the market.	BAREMCUD-TLG-455	39.98
	1970-1974 Ash Tray Bumper - Ea	Factory-style replacement ashtray rubber bumpers for 1970-74 Mopar E-Body models. This bumper measures 7/8" long and features a 1/2" outer diameter. Sold individually.	BAICME509	13.42

	1970-1974 Door Jamb Rubber Seals - PR	Factory-style replacement door jamb rubber "u" seals for 1970-74 Dodge and Plymouth E-Body models. This seal mounts on the rear top edge of the door at the edge of the door glass to prevent moisture from entering the door at the glass at the door jamb. Designed to factory specifications and manufactured in rubber with proper mounting points to correctly replace the door jamb rubber "U" seals. Includes mounting screws. Sold as a pair.	BAICME501	50.38
	1970-1974 E-Body Glove Box/Fuel Door Bumper - Ea	Factory-style replacement rubber bumpers for 1970-74 Mopar E-Body models. This bumper is for both the glovebox door and the fuel door. Sold individually.	BAICME510	16.78
	1970-1974 Heater Box To Cowl Rubber Seal (w/AC)	Replacement heater box to cowl rubber seal for various 1967-74 B-Body, and E-Body models. Manufactured to original specifications out of the correct rubber material. Applications: 1967-70 B-Body w/o air conditioning, 1971-74 B-Body with air conditioning, 1970-74 E-Body with air conditioning.	BAICMD7088	28.54
	1970-1974 Hood Front Bumper - Ea	Factory-style replacement front hood stop bumper for 1970-74 Barracuda and 'Cuda models. Designed to factory specifications to correctly replace the hood stop bumper. Sold individually.	BAICME511	11.74
	1970-1974 Hood Side/Trunk Bumper (Rear/Center Hood) - Ea	Factory-style replacement hood rear center hood stop or trunk bumper for all 1968-74 Mopar B and E-Body models. Designed to factory specifications to correctly replace the hood side stop bumper. This bumper features a 15/16" outer diameter and measures 1-1/8" long. Sold individually.	BAICMD2076	15.10
	1970-1974 Hood Side/Trunk Bumper - Ea	Factory-style replacement hood side stop and trunk bumper for various 1962-65 Mopar B-Body models and 1968-74 B and E-Body models. Designed to factory specifications to correctly replace the hood side stop or trunk bumper. Sold individually.	BAICMD2074	5.02
	1970-1974 Hood To Cowl Seal	Factory-style replacement hood-to-cowl seal for various 1966-70 Mopar B-Body models. This seal helps prevent water and dirt from entering the engine bay. Manufactured to factory specifications in proper materials to correctly replace the hood to cowl seal.	BAICME535	41.98
	1970-1974 Hood To Radiator Seal	Factory-style replacement hood-to-radiator seal for 1970-74 Mopar E-Body models. Manufactured to factory specifications in proper materials to correctly replace the hood to radiator seal.	BAICME536	208.99
	1970-1974 Molded Door Seal End Caps - PR	Factory-style replacement door seal end caps for various 1970-74 Dodge and Plymouth E-Body hardtop and convertible models. This end cap is mounted to the door edge with screws and caps off the edge of the door weatherstrip. Designed to factory specifications for a precise fit, each end cap features a molded-in steel core (when applicable) and is molded with proper contours to correctly replace the door seal end cap. Sold as a pair.	BAICME502	55.42



		1970-1974 Wiper Pivot Gasket Set	Replacement wiper pivot gaskets for all 1971-74 Mopar B-Body and 1970-74 E-Body models. These gaskets are manufactured to the correct original shape to keep water from leaking into the vehicle.	BAICMD600325	6.70
		1971 Fender Mounted Indicator Gaskets (Under) - PR	Replace dried out or missing hood or fender mounted turn signal indicator gaskets with these quality reproduction pieces	BAICMF1713	15.10
		1971 Fender Mounted Indicator Gaskets - PR	Replace dried out or missing hood or fender mounted turn signal indicator gaskets with these quality reproduction pieces	BAICMF1714	16.78
		1971 Park Lamp Lens Gaskets - PR	Replacement park lamp lens gaskets for 1971 Barracuda models. These gaskets are manufactured to fit just like the originals. Sold as a pair.	BAICME5065	15.10
		1971-1974 Inner Fender Rubber Splash Shields - PR	Replacement inner fender splash shields for all 1971-74 Mopar E-Body models. These pieces are mounted to the inner fenders, and are manufactured out of masticated rubber with stainless mounting hardware included.	BAICME861022	33.58
		1972-1974 Park Lamp Lens Gaskets - PR	Replacement park lamp lens gaskets for 1972-74 Barracuda models. These gaskets are manufactured to fit just like the originals. Sold as a pair.	BAICME5066	15.10

Early Birds specializes in hard-to-find Barracuda parts and has been serving you for over 25 years.
Call us at 1 800 463 0546 Mon - Fri 9:00 AM - 4:00 PM (EST) - we know our cars!
Fax your order: (416) 630 8794

Our Mailing Address:
Early Birds
25 Saunders Road, Unit 9
Barrie, Ontario
L4N 9A7
Canada